

True RMS, 3000 A

True RMS, 3000 A

FLEXIBLE AC POWER METER

Model : CWF-3300

ISO-9001, CE, IEC1010



FEATURES :

- * True Power 1800 (KW) measurement.
- * Power Factor (PF) measurement.
- * Apparent Power 1800 (KVA) measurement.
- * Reactive Power 1800 (KVAR) measurement.
- * ACA, ACV, Continuity, ohms, Watt, PF.
- * AC Current (600A, 3000A), auto range .
- * Voltage range : 600 ACV.
- * Voltage and Current measurement are the True RMS value.
- * Heavy duty, CATIII-1000V, 6,000 counts.
- * Flexible Cable length : 280 mm (11 inch).
- * Flexible Cable diameter : 8 mm .
- * Size : 290 x 135 x 27.8 mm.
- * DC 1.5V battery (UM-4, AAA) x 2.

Lutron

LUTRON ELECTRONIC



The Art of Measurement